



Camera adapter is not included with PM5-FM-H8. This item is included with purchase of Flir M132/ M232 camera and is required.





For help e-mail info@seaviewglobal.com ph. 1-800-655-7922